

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



Application Number: 10/630,413

Application Filed: 29 July 2003


Applicant(s): David R. Hinds

Application Title: WALL MOUNTED CLOTHES HAMPER AND SORTER

Examiner/GAU: Miller, William L. /3677

Picture # 1: Shows a woman 5ft. 3inches tall, with a chair in the position/place of a washer or dryer, loading a "Full Size" comforter through the front opening. She is holding the comforter in position while lowering the upper door. The lower door on this prototype was fixed in its location and just hung down from its hinged position.

Picture # 1



Application Number: 10/630,413

Application Filed: 29 July 2003


Applicant(s): David R. Hinds

Application Title: WALL MOUNTED CLOTHES HAMPER AND SORTER

Examiner/GAU: Miller, William L. /3677

Picture # 2: Shows a woman 5ft. 3inches tall, with a chair in the position/place of a washer or dryer, loading a large wadded up towel (46x27 inch) through the upper front opening with the upper door in the full down position. The lower door on this prototype was fixed in its location and just hung down from its hinged position.

Picture # 2



Application Number: 10/630,413

Application Filed: 29 July 2003


Applicant(s): David R. Hinds

Application Title: WALL MOUNTED CLOTHES HAMPER AND SORTER

Examiner/GAU: Miller, William L. /3677

Picture # 3: Shows a woman 5ft. 3inches tall, with a chair in the position/place of a washer or dryer, unloading a "Full Size" comforter through the front opening with the upper door in its 2/3's open position. The lower door on this prototype was fixed in its location and just hung down from its hinged position.

Picture # 3



Application Number: 10/630,413

Application Filed: 29 July 2003


Applicant(s): David R. Hinds

Application Title: WALL MOUNTED CLOTHES HAMPER AND SORTER

Examiner/GAU: Miller, William L. /3677

Picture # 4: Shows this improved prototype placed in a chair, with the front edge of the prototype just extended past the front edge of the chair, with the upper and lower doors engaged and closed for improved appearance.

Picture # 4



Application Number: 10/630,413

Application Filed: 29 July 2003


Applicant(s): David R. Hinds

Application Title: WALL MOUNTED CLOTHES HAMPER AND SORTER

Examiner/GAU: Miller, William L. /3677

Picture # 5: Shows this improved prototype placed in a chair, with the front edge of the prototype just extended past the front edge of the chair, with the upper door in the full open/raised position and the lower door in the full lowered and nonstowed position.

Picture # 5



Application Number: 10/630,413

Application Filed: 29 July 2003


Applicant(s): David R. Hinds

Application Title: WALL MOUNTED CLOTHES HAMPER AND SORTER

Examiner/GAU: Miller, William L. /3677

Picture # 6: Shows this improved prototype placed in a chair, with the front edge of the prototype just extended past the front edge of the chair, with the upper door in the full open/raised position and the lower door in the full lowered and stowed position.

Picture # 6



Application Number: 10/630,413

Application Filed: 29 July 2003

Applicant(s): David R. Hinds

Application Title: WALL MOUNTED CLOTHES HAMPER AND SORTER

Examiner/GAU: Miller, William L. /3677

Picture # 7: Shows this improved prototype placed in a chair, with the front edge of the prototype just extended past the front edge of the chair, with the upper door in the full down position and the lower door in the full lowered and stowed position.

Picture # 7